


09/940,282.

copy

BLAKELY SOKOLOFF TAYLOR & ZAFMAN

A LIMITED LIABILITY PARTNERSHIP INCLUDING LAW CORPORATIONS



TELEPHONE (408) 720-8300
FACSIMILE (408) 720-8383

BSTZ_MAIL@BSTZ.COM
WWW.BSTZ.COM

INTELLECTUAL PROPERTY LAW

SILICON VALLEY

1279 OAKMEAD PARKWAY
SUNNYVALE, CALIFORNIA 94085-4040

OTHER OFFICES

LOS ANGELES, CA
ORANGE COUNTY/COSTA MESA, CA
SAN JOSE, CA
DENVER, CO
PORTLAND/BEAVERTON, OR
SEATTLE, WA

February 24, 2005

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Certificate
MAR 15 2005
of Correction

Re: CERTIFICATE OF CORRECTION
U. S. Letters Patent No. 6,839,854
Issued: January 4, 2005
For: VOLTAGE REGULATION FOR COMPUTER
SYSTEM COMPONENTS THAT INCREASES
VOLTAGE LEVEL WHEN A COMPONENT
ENTERS A SLEEP STATE AS INDICATED BY
A POWER STATE STATUS SIGNAL

Inventor: Nguyen
Our File No. 42390.P12726

Dear Sir:

Enclosed is the Certificate of Correction (two copies) for the above-referenced patent.
This request for correction is made under rule 322 of the Rules of Practice and 35 U.S.C.
Section 254.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP


Edwin H. Taylor

Reg. No. 25,129

EHT/jsq
Enclosures

MAR 15 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,839,854

DATED : January 4, 2005

INVENTOR(S) : Nguyen

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 8, at line 7 before "second", insert --a--.

In column 8, at line 22, delete "signal" and insert --signals--.

In column 8, at line 22, delete "SLP₁₃S3#" and insert --SLP_S3#--.

In column 9, at line 24, delete "processors" and insert --processor--.

In column 9, at line 27, delete "arid" and insert --and--.

In column 10, at line 45, delete "SLP₁₃S3#" and insert --SLP_S3#--.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,839,854

Certificate of Correction (PTO Form 1050)-Amended

MAR 15 2005

MAR 15 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,839,854

DATED : January 4, 2005

INVENTOR(S) : Nguyen

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 8, at line 7 before "second", insert --a--.

In column 8, at line 22, delete "signal" and insert --signals--.

In column 8, at line 22, delete "SLP₁₃S3#" and insert --SLP_S3#--.

In column 9, at line 24, delete "processors" and insert --processor--.

In column 9, at line 27, delete "arid" and insert --and--.

In column 10, at line 45, delete "SLP₁₃S3#" and insert --SLP_S3#--.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,839,854

Certificate of Correction (PTO Form 1050)-Amended

MAR 15 2005